

Results of treatments on cars done by the XADO Service Centre

Test 1:

BMW				
Model	BMW318 (1985) Total Kilometres Logged: 226,913			
Compression in cylinders				
	Cylinder 1	Cylinder 2	Cylinder 3	Cylinder 4
Before Treatment	13.5	12.5	11.5	13.5
After Treatment	14.5	13.5	14.5	14.5

Test 2:

FORD				
Model	Ford Escort – Saloon (1989)			
Compression in cylinders				
	Cylinder 1	Cylinder 2	Cylinder 3	Cylinder 4
Before Treatment	9.0	8.0	9.0	10.0
After Treatment	11.5	9.5	13.0	12.0

Test 3:

FORD				
Model	Ford Sierra (1988)			
Compression in cylinders				
	Cylinder 1	Cylinder 2	Cylinder 3	Cylinder 4
Before Treatment	10.5	8.0	10.0	10.5
After Treatment	12.0	12.7	13.0	13.0

Test 4:

Mitsubishi				
Model	Mitsubishi Cardia (1986) Total Kilometres Logged: 278,085			
Compression in cylinders				
	Cylinder 1	Cylinder 2	Cylinder 3	Cylinder 4
Before Treatment	13.0	13.0	13.5	12.5
After Treatment	15.0	14.5	15.0	15.0

Test 5:

Citroen				
Model	Citroen XM(1991) Total Kilometres Logged: 146,476			
Compression in cylinders				
	Cylinder 1	Cylinder 2	Cylinder 3	Cylinder 4
Before Treatment	11.0	9.0	9.5	12.0
After Treatment	13.5	12.5	13.5	13.0